



C368 SOFTWARE RELEASE NOTES

MCU 1.74

C368 software update MCU 1.74 is a maintenance release that includes the following change:

- Firmware support for MDC USB DSD*

** Applies to units with the optional MDC USB DSD module installed*

Software Package

C368 MCU 1.74 software package includes the following software version details:

- Main : V1.74

It is not necessary to upgrade VFD and BT software versions as they remain the same.

- VFD : V1.22
- BT : V1.26